

# Sensors and Process Instruments

PRODUCTS AND SOLUTIONS FOR AUTOMATION,
QUALITY ASSURANCE AND PRODUCTION MONITORING

Model **8628** 

#### **Technical Data**

Order Code	Measuring	g	Dimensions [mm]								Bore Holes	
	Range	øΑ	øΒ	øD	F	G	L	øΤ	øQ	Number	Pitch	
8627-5010-VXXXXX	0 ± 10	Nm 20 <sup>H7</sup>	10	70	12	M8	65	58	45	6	60°	33
8627-5020-VXXXXX	0 ± 20	Nm 20 <sup>H7</sup>	10	70	12	M8	65	58	45	6	60°	33
8627-5050-VXXXXX	0 ± 50	Nm 20 <sup>H7</sup>	10	70	12	M8	65	58	45	6	60°	33
8627-5100-VXXXXX	0 ± 100	Nm 20 <sup>H7</sup>	10	70	12	M8	65	58	45	6	60°	33
8627-5200-VXXXXX	0 ± 200	Nm 20 <sup>H7</sup>	10	70	12	M8	65	58	45	6	60°	33
8627-5500-VXXXXX	0 ± 500	Nm 20 <sup>H7</sup>	18	100	15	M10	80	82	60	8	45°	39.5
8627-6001-VXXXXX	0 ± 1000	Nm 20 <sup>H7</sup>	18	100	15	M10	80	82	60	8	45°	39.5
8627-6002-VXXXXX	0 ± 2000	Nm 75 <sup>H7</sup>	20	130	20	M12	100	100	80	12	30°	45
8627-6005-VXXXXX	0 ± 5000	Nm 75 <sup>H7</sup>	20	130	20	M12	100	100	80	12	30°	45

Higher measuring ranges upon request

# Electrical values

Resistor bridge (full bridge): foil strain gauge 350  $\Omega$ , nominal\* \* Deviation from the indicated values are possible.

Excitation voltage: 2 ... 12 V recommended 10 V Nominal value: standard, 1 mV/V 10 Nm and 50 Nm: 0.5 mV/V

#### Environmental conditions

Operating temperature range: - 15 °C ... + 55 °C - 5 °C ... + 45 °C Rated temperature range:

Temperature effect: on zero signal: ± 0.02 % F.S./K on characteristic value: ± 0.01 % F.S./K

#### Mechanical values

Relative linearity error: ± 0.1 % F.S. Relative reversibility error: ± 0,1 % F.S. Relative repeatability error: ± 0,1 % F.S. Max. operating torque (static): 150 % of nominal value Torque limit (static): 200 % of nominal value Breaking moment (static): > 300 % of nominal value Dynamic load: recommended ≤ 70 % of nominal value Rated torsion angle: < 0.1° Material: steel, 1.2826 res. 1.2738


Degree of protection: acc. EN 60529

Pins assignment:


Pin
1
2
3
4
5
6

Mechanical connection: both ends with flag Electrical connection: 6 pins plug connection 6 pole model 9953 Mating: (included is scope of delivery)

# Application



# Dimension drawing model 8627



The CAD drawing (3D/2D) for this sensor can be imported online directly into your CAD system.

Download via www.burster.com or directly at www.traceparts.com. For further information about the burster traceparts cooperation refer to data sheet 80-CAD-EN.

#### Order Information

Torque sensor, non-rotary, both ends with flags, burster TEDS, measurement ±100 Nm Model 8627-5100-V00430

#### **Options**

IP50

Torque sensor	Model 8627-XXXX-V00 ☐ 30
with mV/V output, standardized	3
with mV/V output, burster TEDS	4

### Accessories

Model 9953 Mating connector, 6 pole cable coupling Mating connector, 6 pole, 90°- phase shift Model 9900-V589

Connection cable with one end free, length 3 m,

Model 99553-000A-0110030 with connector model 9953 Connection cable, length 3 m

for burster desktop instruments with 12 pin connectors

Model 99141-553A-0150030 for model 9235, model 9311 and model 7281

Model 99209-553A-0110030

Amplifier, process indicators, digital displays

see section 9 of the catalog.

## Manufacturer Calibration Certificate (WKS)

Special calibration for clockwise or/and counter clockwise direction torque, in 20 % steps of range up and down.



**Torque Sensor** For static and dynamic applications, non-rotary **Model 8628** 

Code: 8628 EN Delivery: 4 weeks Warranty: 24 months





- Measurement range from 0 ... 2 Nm to 0 ... 1000 Nm
- Linearity error 0.2 % F.S.
- Reliable and durable
- Simple handling and assembly
- Output signal standardized
- Different mechanical versions
- Special versions and higher measurement ranges on request
- Optional linearity error 0.1 % F.S.

#### **Application**

The 8628 torque sensor is suitable for both static and dynamic measurements in non-rotating torque-transmission systems. Typical uses include testing and calibrating power screwdrivers and torque wrenches and measuring reactive torques on test benches.

For individual measuring tasks the design of our torque sensors can be adapted to the customer's installation conditions.

More application examples:

- ► Test structures in the field of precision mechanics
- ▶ Determination of friction torques
- ► Acquisition of breakage moments on screw caps

Technical changes reserved. All data sheets at www.burster.com

► Quality assurance in power screwdrivers

#### Description

The design has been optimized regarding overall length, weight and volume, so that axial forces up to relatively high limit values and bending moments of up to 20 % of the measuring range have only a small effect to the influence of the measuring element. Four metal film strain gauges are mounted on the measuring element and connected to form a full bridge. When applying AC or DC voltage on the bridge, the mechanical value torque is converted into electrical voltage. The necessary amplifier either delivers a norm signal (0 ... 10 V, 0/4 ... 20 mA) or – with indicator module – a torque signal truly corresponding to the measured variable.

The sensor output signal is standardized, so that an exchange of the sensor (spare part) does not require any new adjustment of the measuring chain.